





NH 1-2-3




1.




Eemalda klemmide kate ja tõmba käepidemest


2.1



2.2.









3.1.



Slaid 3.1 - Kinnita kaabliklemmid ja ühenda kaablid.
Paigalda klemmide kate

Slaid 2.2 on sulavkaitaselüliti paigaldamiseks pingestatud lattidele.
Vaata pingeluste tööde juhendit.



TRIVER+			
	250 A	400 A	630 A
Ie(A)	250	400	630
Ue(V)	690	690	690
	NH1	NH2	NH3
Ui(V)	1000	1000	1000
Ui (KV) 50Hz – 1 min			
L1-L2_L3 (L1-L2-L3) –	3.5 10	3.5 10	3.5 10
Uimp (kv)	20	20	20
Icm (kA)	>50	>50	>50
Ri (MOHM)	>5	>5	>5
Icm/Ie-			
400V	AC-23B	AC-23B	AC-22B
500V	AC-22B	AC-22B	AC-22B
690V	AC-22B	AC-22B	AC-22B